

H-21



How to install the protective film rev 1.00

1. Precautions

The working environment needs to be clean.

Items you need:

- H-21.
- Protective film
- Lint free cloth



H-21




Protective film



Lint free cloth

2. Instructions

- Set up a workspace in a room as clean and dust-free as you can find. Clear your work surface of other objects and wipe down with a wet cloth. Have the protective film close at hand. Time is of the essence for avoiding dust accumulation.
- Turn the H-21 device off / remove the main battery. You won't want the screen to come on while you're working. Remove the plastic nylon on the H-21 display.



- Clean the surface of the touch screen with a lint free cloth if there is / are dust or fingers prints.



- Smoothly remove half of the protective film from its backing to expose the adhesive and lower it into place, starting from the rear end of the H-21 touch lens. It is far more important to avoid dust! Do not touch the touch screen or the back of the film during the installation.



- Apply the rest of the film by peeling the remainder of the backing off and letting the film drop onto the LCD screen. The best way to do it is to keep tension on the actual film itself and slowly let it fall all the way making sure no bubbles form.



Don't panic when you see all the air bubbles! Use a lint free cloth to remove any bubbles, work from the center of the screen out toward the edges. Do not use any hard tool or spatula on the film to avoid scratches.

Smoothly remove the nylon cover that protects the protective film from the top side.

